



This Service Information bulletin supersedes SI B64 12 07 dated **September 2007**.

NEW designates changes to this revision

SUBJECT

White Flakes/Powder Coming from the Air Conditioning Vents

MODEL

E90, E91, E92, E93 (3 Series)

Vehicles produced from May 31, 2006 to September 9, 2007

SITUATION

The customer states that at times white flakes or powder comes from the air conditioning vents.

CAUSE

Surface oxidation of the evaporator. This only concerns evaporators manufactured by Denso (identified by the label on the front of the air conditioning housing behind the radio).

NEW PROCEDURE

1. Replace the evaporator.
2. Clean the heating and air conditioning housing and the air ducts to remove any residual flakes or powder. (Simply wipe with a damp cloth. Do not use any cleaning agents.)

NEW PARTS INFORMATION

Part Number	Description	Quantity
64 11 9 179 802	Evaporator (Denso)	1

NEW WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Please refer to the latest KSD for all applicable labor operations and allowances.

If the appropriate labour operation is not contained in KSD, then a work time labour operation shall be used.

Defect Code **64 51 00 78 00**