



Car data



13:06

28.01.2010

		Original	User specif.
VIN Number	WVWZZZ6NZYD517761	Engine Code	AGD
Sales Type	6N2034	Transmission Code	ETF
Model Year	2000	Finaldrive Ident	5S
Model	PO	Interior trim code	MQ
Model Designation	polo 1,9 sdi	Roof Color	Z4
		Exterior Color	Z4

PR Numbers

A8C	Comfort equipment
B0A	Component parts set without country-specific design requirement
B14	Type approval Italy (San Marino, Vatican City)
C08	Operating permit, alteration
C8E	Steel wheels 6J x 14 Offset 43
E0A	No special edition
F0A	No special purpose vehicle, standard equipment
G0C	5-speed manual transmission
GP1	Vehicles with special upgrade measures
H2Y	Tires 185/55 R14 H
J0N	Battery 330 A (61 Ah)
K8G	Hatchback
L0L	Left-hand drive vehicle
M16	4-cylinder diesel engine 1.9 L/47 kW SDI with MVEG 2 base engine is T2Q
N0U	Cut pile seat covering
Q1W	Standard front seats with integrated storage trays
T2Q	4-cylinder diesel engine 1.9 L unit 028.H
U0C	Instrument insert with tachometer clock and km/h speedometer
V0A	Tires w/o specification of tire brand
0A2	4 doors
0AB	Front stabilizer
0BA	Without rear stabilizer
0DH	Vehicle class differentiation 6N0
0F3	Fuel system for diesel engine
0FK	Bratislava manufacturing sequence
0GD	Emission standard EU2 MVEG 2
0JZ	Without determination of weight category for front axle
0KA	Without stickers and badges
0L2	Electric throttle actuation
0RA	Without ignition/starter switch locking system



Car data



13:06

28.01.2010

PR Numbers

0SK	Labels/plates in Italian
0TD	Front and rear floor mats
0UA	Without special color trim
0Y1	Standard climatic zones
1AL	Power brake
1C1	Antifreeze up to -25 degree celsius tolerance up to -30 degree C
1E0	Without activated charcoal canister
1EX	Special identification plate for EC for M1 passenger vehicle
1G6	Space-saving spare wheel
1K1	Mechanical clutch actuation
1KH	Drum brakes, rear
1LB	Disc brakes, front
1MZ	Steering wheel for air bag system
1N1	Power steering
1NV	Full wheel covers
1S4	Tool kit with special jack
1T0	Without first aid kit and warning triangle
1Z0	Initial standard fuel filling
2B3	Additional exterior noise suppression (hood, capsule and dash panel)
2G0	Without insert for the filling up of fuel
2JF	Painted bumpers
2LA	Fuel tank without special material treatment
2V1	Dust and pollen filter
2VG	Nameplate set "SDI" in base trim
2WA	Without additional tires
3B0	Without additional child seat anchor
3C1	Static lap belt, center rear
3CA	Without partition
3FA	Without roof insert (standard roof)
3GA	Without cargo area
3H0	Without backrest release for front seats
3J7	Articulated and height-adjustable headrests for front seats
3L3	Manual height adjustment for front seats
3LD	Door and side trim panel
3NC	Rear seat bench/backrest, split folding
3Q1	Rear headrests
3QT	3-point seat belts with tensioner and height adjustment, front
3U1	Foldable trunk cover
3ZB	3-point seat belts, outer rear with ECE label
4A0	Without seat heater
4B1	Protective side molding
4F1	Central locking system
4GF	Windshield in heat-insulating glass
4KC	Side and rear windows in heat-insulating



Car data



13:06

28.01.2010

PR Numbers

	glass
4L2	Dipping breakaway interior rear view mirror
4M5	Cup holder
4N2	Standard dashboard
4Q0	No flame retardent materials
4R2	Power windows front, mechanical window regulators rear
4UE	Air bag for driver and front seat passenger
4W0	Without cassette and CD storage unit
4X1	Side air bag front
5C0	Without special body measures
5D0	Without carrier frequency
5J0	Without rear spoiler
5K1	Paint preservative (wax)
5L1	Front spoiler
5RQ	Right exterior mirror: convex
5SL	Left exterior mirror: aspherical
5VA	Without cargo area front
6EJ	Additional body cover on sill without wheel arch
6FA	Components without special surface appearance
6KA	Radiator grille
6N0	Without mud flaps
6PA	Plastic hand brake lever handle
6Q1	Plastic gearshift knob/handle
6R1	Leatherette gearshift boot
6SE	Flat needle-punched trunk floor covering
6U0	Without additional seals outside
6XD	Exterior mirrors: electrically adjustable/heated
6Y0	Without cruise control warning system
7A0	Without CD changer/CD player
7AA	Electronic vehicle immobilization device
7B2	12-volt socket in luggage boot
7E0	W/o heat accumulator/auxiliary heating
7Q0	Without navigation device
7QA	Without CD/DVD for navigation
7R3	Side turn signal lights (white)
8AA	Without radio
8BB	Halogen headlight for driving on the right
8CC	Speedometer sensor without seal (electronic speedometer sensor)
8E0	Without interference suppression
8GD	Alternator 90A
8K0	Without special headlight activation
8N1	Windshield wiper intermittent control
8Q1	Headlight-range adjustment
8QB	Key with LED and inscription



Car data



13:06

28.01.2010

PR Numbers

8R1	Center high-mounted stop light
8RE	4 speakers (passive)
8SB	Taillight assembly w/ dark colored lens
8TC	Rear fog light for driving on the right
8WD	Integrated front fog light
8X0	Without headlight washer system
8Y0	Single-tone horn
9AA	Manually controlled heating system
9P0	Without seat belt reminder
9T1	Heated washer nozzles, front
9W0	W/o car phone preparation/installation
9Y0	Without outdoor temperature gage